

*City of Anaheim*  
*Facilities*  
*ADA Compliance Survey Report*  
*FY 92/93*

*City of Anaheim*  
*Facilities*  
*ADA Compliance Survey Report*  
*FY 92/93*

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

<b>Facilities</b>	<b>Grand Total</b>	<b>Total Est. Cost FY 93/94</b>	<b>Total Est. Cost FY 94/95</b>	<b>Total Est. Cost FY 95/96</b>
Anaheim Senior Citizens Center	6,320	3,170	1,150	2,000
George Washington Community Center	2,850	1,200	1,650	0
Jeffrey Lynn Community Center	4,575	4,575	0	0
West Anaheim Senior Citizens Center	5,970	5,970	0	0
<b>Community Centers Total</b>	<b>\$19,715</b>	<b>\$14,915</b>	<b>\$2,800</b>	<b>\$2,000</b>
Canyon Library	3,550	2,150	1,400	0
Central Library	120,330	6,630	29,700	84,000
Euclid Library	37,225	1,425	0	35,800
Haskett Library	37,475	875	800	35,800
Sunkist Library	37,975	1,325	0	36,650
<b>Libraries Total</b>	<b>\$236,555</b>	<b>\$12,405</b>	<b>\$31,900</b>	<b>\$192,250</b>
Gober Park	11,550	900	2,000	8,650
Imperial Park	0	0	0	0
Pearson Park	11,490	1,990	0	9,500
<b>Parks Total</b>	<b>\$23,040</b>	<b>\$2,890</b>	<b>\$2,000</b>	<b>\$18,150</b>
Brookhurst Community Center	8,570	3,250	5,320	0
Martin Recreation Center	37,100	650	0	36,450
Oak Canyon Nature Center	1,050	750	0	300
<b>Recreation Centers Total</b>	<b>\$45,670</b>	<b>\$3,900</b>	<b>\$5,320</b>	<b>\$36,450</b>
City Hall Public Areas	\$139,700	\$46,200	\$36,000	\$57,500
Convention Center	\$206,600	\$21,600	\$15,500	\$169,500

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

<i>Facilities</i>	<i>Grand Total</i>	<i>Total Est. Cost FY 93/94</i>	<i>Total Est. Cost FY 94/95</i>	<i>Total Est. Cost FY 95/96</i>
<i>Utility Service Center</i>	<i>\$17,500</i>	<i>\$0</i>	<i>\$17,300</i>	<i>\$200</i>

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**ANAHEIM SENIOR CITIZENS CENTER**

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost</i>	<i>Est. Cost</i>	<i>Est. Cost</i>
<i>2nd flr Women's restroom</i>	<i>Entry width not adequate</i>	<i>Use first floor unisex restroom as alternate</i>			
	<i>Commode 15" off ground (4.16.3)</i>	<i>Install raised seat to meet requirement</i>	\$120		
	<i>Mirror is too high (4.19.6)</i>	<i>Install extended mirror</i>	\$250		
	<i>Faucet controls are not handicap (4.19.5)</i>	<i>Install push-type faucet</i>	\$300		
<i>2nd flr Men's restroom</i>	<i>Entry width not adequate</i>	<i>Use first floor unisex restroom as alternate</i>			
	<i>Sink without handle (4.27.4)</i>	<i>Install push-type faucet</i>	\$300		
	<i>Urinal too high (4.18)</i>	<i>Lower urinal</i>	\$700		
<i>Administrative offices</i>	<i>Need handle to replace knobs (4.27.4)</i>	<i>Install lever handles on doors</i>	\$900		
<i>Stage area</i>	<i>No handicapped access (4.33.5)</i>	<i>Install lift or ramp 36"</i>			\$2,000
<i>Drinking fountain</i>	<i>Handles (4.27.4), height questionable</i>	<i>Replace fountain</i>		\$850	
<i>Parking</i>	<i>No van parking (4.1.2.b)</i>	<i>Re-stripe parking add van parking</i>	\$600		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>		\$300	

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

ANAHEIM SENIOR CITIZENS CENTER

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost</i>	<i>Est. Cost</i>	<i>Est. Cost</i>
	\$6,320		\$3,170	\$1,150	\$2,000
<b>Grand Total:</b>			<b>Total For Fiscal Year:</b>		

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

GEORGE WASHINGTON COMMUNITY CENTER

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Men's restroom (2)	No mirror (4.19.6)	Repeated vandalism - not cost effective to replace	N/A		
Stage area	No ramp (4.33.5)	Install ramp approx.. 14"	\$500		
Building	Threshold in 3 interior locations too high (4.13.8) 1. Anaheim senior day center room 2. Legal AID Society room 3. State/Youth Employment room			\$550 \$550 \$550	
Parking area	No warning signs (4.30) Re-paint stall marking (4.30)	Install warning signs Repaint pavement marking	\$300 \$400		
<b>Grand Total:</b>	<b>\$2,850</b>		<b>\$1,200</b>	<b>\$1,650</b>	<b>\$0</b>

**Total For Fiscal Year:**

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

JEFFREY LYNN COMMUNITY CENTER

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Restroom (unisex)</i>	<i>Door width 2.' inadequate (4.22)</i>	<i>Install 3.0 door and lever type handle</i>	<i>\$1,500</i>		
	<i>Sink height and clearance inadequate (4.27.3)</i>	<i>Install new sink</i>	<i>\$750</i>		
	<i>Commode to low</i>	<i>Install floor mount handicap commode</i>	<i>\$350</i>		
	<i>No grab bars around commode</i>	<i>Install wall and floor mount grab bars 2 sides min.</i>	<i>\$400</i>		
	<i>Soap/towel dispenser</i>	<i>Install dispensers as required at appropriate height</i>			
<i>Parking</i>	<i>Street parking only, no ramps (4.8)</i>	<i>Install ramps</i>	<i>\$1,500</i>		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>	<i>\$75</i>		
<b><i>Grand Total:</i></b>	<b><i>\$4,575</i></b>		<b><i>\$4,575</i></b>	<b><i>\$0</i></b>	<b><i>\$0</i></b>

*Total For Fiscal Year:*

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

WEST ANAHEIM SENIOR CITIZENS CENTER

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Entrance</i>	<i>handrail is too large in diameter should be 1 1/2" diameter (4.26.2)</i>	<i>Would not be cost effective to replace - minimal gain</i>	<i>n/a</i>		
<i>Women's restroom</i>	<i>Commode 15" off ground (4.16.3)</i>	<i>Replace seat with raised type to meet standard</i>	<i>\$120</i>		
	<i>Mirror too high (4.19.6)</i>	<i>Replace mirror with extened type</i>	<i>\$150</i>		
<i>Men's restroom</i>	<i>Sink without handle(4.27.4)</i>	<i>Replace fixture to meet standard</i>	<i>\$200</i>		
	<i>Urinal too high (4.18)</i>	<i>Lower urinal</i>	<i>\$600</i>		
<i>Administrative offices</i>	<i>Need handle to replace knobs (4.13.9)</i>	<i>Change door hardware with approved type</i>	<i>\$400</i>		
<i>TLC Room</i>	<i>Doorway inaccessible, should be 32" (4.13.5)</i>	<i>Frame doorways replace door and trim</i>	<i>\$1,800</i>		
<i>Stage area</i>	<i>No handicapped access (4.33.5)</i>	<i>Build lift or ramp</i>	<i>\$1,500</i>		
<i>Drinking fountain</i>	<i>Handles (4.27.4), height questionable</i>	<i>Replace fountain</i>	<i>\$800</i>		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>	<i>\$400</i>		
<b><i>Grand Total:</i></b>	<b><i>\$5,970</i></b>		<b><i>\$5,970</i></b>	<b><i>\$0</i></b>	<b><i>\$0</i></b>

**Total For Fiscal Year: \$5,970 \$0 \$0**

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**CANYON LIBRARY**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
Parking stalls	Need four additional stalls, one van (4.1.2.b)	Add new handicapped stalls	\$450		
Drinking fountain	Side handles inaccessible (4.27.4)	Install new push-type handles		\$800	
Men's restroom	No handles on sink (4.24.7)	Install push-type handle	\$450		
	No grab bar at the back of commode (4.26)	Install grab bar	\$200		
	No wrap for drain ((4.24.6)	Add wrapping	\$50		
Women's restroom	No handles on sink (4.24.7)	Install push-type handle	\$450		
	No grab bar at the back of commode (4.26)	Install grab bar	\$200		
	No wrap for drain ((4.24.6) Mirror is too high (4.19.2)	Add wrapping Lower mirror	\$50 \$300		
General	Handicapped signage (4.30)	Install when accessibility complete		\$600	
<b>Grand Total:</b>	<b>\$3,550</b>		<b>\$2,150</b>	<b>\$1,400</b>	<b>\$0</b>

**Total For Fiscal Year: \$2,150**

**\$1,400**

**\$0**

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

CENTRAL LIBRARY

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost	Est. Cost	Est. Cost
			FY 93/94	FY 94/95	FY 95/96
Front Entrance	Length 30ft, should be 34 ft. (4.8.2)	Cost exceed benefit for change of 10% slope	N/A	N/A	N/A
Pay phone Lobby	Needs warning device for blind within 9" of ground (4.4.1)	Install device	\$380		
Children boy's room	Not in compliance (4.23)	Construct unisex restroom for handicap		\$28,000	
Children girl's room	Not in compliance (4.23)	Construct unisex restroom for handicap			\$28,000
Front counter	24" clearance, should be between 28" and 34" (4.32.4)	Clerk to assist handicapped patrons - include appropriate signage	\$200		
Drinking fountain	Not front mounted (4.15.4)	Replace fountain		\$850	
	Does not extend 9" form ground (4.15.2)				
Elevator	No bells or audible signals (4.10.4)	Add visual and audible signals			\$3,500
	No star indicator (4.10.12)	Add visual and audible signals			
	Control too high, no visual signals (4.10.12)	Lower controls to within armchair reach			\$14,000

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

CENTRAL LIBRARY

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Stairs	Landing needs texture different from rest of carpet, handrail not continue out stops at landing (4.9.4)	Change stain tread to vinyl type in contrasting color	\$5,800		
Second floor drinking fountain	Does not have "skirt" 9" off ground (4.15.2)	Replace fountain		\$850	
Second floor Men's staff room	Door handles are knobs, need levers (4.24.7) Commode height wrong (4.17) Stall height too narrow (4.17) No wrapping (4.24.6) No mirror (4.19.6) Sink without handle (4.24.7)	Install push knobs See 1st floor children's restroom	\$250		
Women's room	Door handles are knobs, need levers (4.24.7) Commode height wrong (4.17) Stall height too narrow (4.17) No wrapping (4.24.6) No mirror (4.19.6) Sink without handle (4.24.7)	Install push knobs Add public handicap unisex rest room for exclusive handicap use. See 1st floor children's restroom			
Basement restroom	Commode height wrong (4.17)	Add public handicap unisex rest room for exclusive handicap use. see 1st floor children's restroom			

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

CENTRAL LIBRARY

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Basement Women's restroom</i>	<i>Stall height too narrow (4.17)</i>	<i>Add public handicap unisex rest room for exclusive handicap use. see 1st floor children's restroom</i>			
	<i>No wrapping (4.24.6)</i>				
	<i>No mirror (4.19.6)</i>				
	<i>Sink without handle (4.24.7)</i>				
<i>Staff Breakroom Men's</i>	<i>No wrapping (4.24.6)</i>	<i>Add public handicap unisex rest room for exclusive handicap use. see 1st floor children's restroom</i>			
	<i>Sink without handle (4.24.7)</i>				
	<i>Mirror too high (4.19.6)</i>				
	<i>No signage (4.30)</i>				
<i>Staff Breakroom Women's</i>	<i>Not handicap accessible</i>	<i>Add public handicap unisex rest room for exclusive handicap use. see 1st floor children's restroom</i>			
	<i>No visual (4.28.3)</i>				
<i>Fire alarm</i>	<i>Handicapped signage (4.30)</i>	<i>Add visual alarm if audible is provided</i>			<i>\$36,000</i>
<i>General</i>		<i>Install when accessibility complete</i>			<i>\$2,500</i>
<b><i>Grand Total:</i></b>	<b><i>\$120,330</i></b>		<b><i>\$6,630</i></b>	<b><i>\$29,700</i></b>	<b><i>\$84,000</i></b>
		<b><i>Total For Fiscal Year:</i></b>	<b><i>\$6,630</i></b>	<b><i>\$29,700</i></b>	<b><i>\$84,000</i></b>

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**EUCLID LIBRARY**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
<b>Parking</b>	No van stalls (4.1.2.b)	Re-draw or combine lanes	\$500	N/A	N/A
<b>Men's restrooms</b>	Sink 27" high, should be 34" (4.24.2) Urinal is too high 23" (4.18.2) No wrap for drain (4.24.6) No signage (4.30.7) Not adequate access (see unisex below)	Lower sink Lower urinal maximum of 17" above floor Add wrapping Add signage Not adequate access (see unisex below)	N/A	N/A	N/A
<b>Women's restroom</b>	No wrapping (4.24.6), no signage No signage (4.30.7) Not adequate access (see unisex below)	Add wrapping and signage Add signage Not adequate access (see unisex below)			
<b>Add unisex restroom</b>	Public men's and women's restrooms access inadequate (4.22)	Construct unisex restroom for exclusive handicap use			\$35,000
<b>Drinking fountain</b>	Need addition to base for blind (4.15.5)	Install new fountain		\$850	
<b>Staff unisex restroom</b>	Flush not accessible (4.24.7) Pipe need wrap (4.24.6) Opening only 29" (4.13.5)	Change flush to push-type control Add wrapping Widen opening	N/A	N/A	N/A
<b>Book rows</b>	32" wide, need 36" (4.3.3, 8.5)	Clerk to assist patrons - Install assistance signage			\$75

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

EUCLID LIBRARY

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Front counter</i>	<i>38" high, should be 34" (7.2)</i>	<i>Clerk to assist patrons - Install assistance signage</i>	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>
<i>Parking stalls</i>	<i>Five more handicapped stalls needed, with one van accessible (4.1.2.b)</i>	<i>Re-draw or combine lanes</i>	<i>\$850</i>		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>			<i>\$800</i>
<b><i>Grand Total:</i></b>	<b><i>\$37,225</i></b>		<b><i>\$1,425</i></b>	<b><i>\$0</i></b>	<b><i>\$35,800</i></b>

*Total For Fiscal Year:*

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

HASKETT LIBRARY

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY95/96</i>
<i>Parking stall</i>	<i>Need 5 more stalls, one a van (4.1.2.b)</i>	<i>Re-draw or combine lanes</i>	<i>\$800</i>		
<i>Add unisex restroom</i>	<i>Public men's and women's restroom access inadequate (4.22)</i>	<i>Construct unisex restroom for exclusive handicap use</i>			<i>\$35,000</i>
<i>Book stalls</i>	<i>32.5" clearance (8.5, 4.3)</i>	<i>Install assistance signage min 36"</i>	<i>\$75</i>		
<i>Staff restroom</i>	<i>Door width 29", need handles (4.13.5)</i>	<i>Use unisex handicap restroom when complete</i>			<i>N/A</i>
<i>Drinking fountain</i>	<i>Mounted on side, not from (4.15.4)</i>	<i>Replace with handicap approved</i>		<i>\$800</i>	
<i>Telephone</i>	<i>Needs visually impaired "skirt" (4.4.1)</i>	<i>Modify as needed (Pac Bell)</i>	<i>N/A</i>		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>			<i>\$800</i>
<b><i>Grand Total:</i></b>	<b><i>\$37,475</i></b>		<b><i>\$875</i></b>	<b><i>\$800</i></b>	<b><i>\$35,800</i></b>

*Total For Fiscal Year:*

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**SUNKIST LIBRARY**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
<i>Parking stall</i>	<i>Need 5 more stalls, one van (4.1.2.b)</i>	<i>Re-draw or combine lanes</i>	<i>\$800</i>		
<i>Front Entrance</i>	<i>Opening too heavy, max 151bf (4.13.12)</i>	<i>Replace door closer</i>	<i>\$450</i>		
<i>Add unisex restroom</i>	<i>Public men's and women's restroom access inadequate (4.22)</i>	<i>Construct unisex restroom for exclusive handicap use</i>			<i>\$35,000</i>
<i>Book stalls</i>	<i>32.5" clearance (8.5, 4.3)</i>	<i>Clerk to assist patrons - Install assistance signage</i>	<i>\$75</i>		
<i>Staff restroom</i>	<i>29" opening, need handles (4.13.5)</i>	<i>Use unisex handicap restroom when complete</i>	<i>N/A</i>		<i>N/A</i>
<i>Drinking fountain</i>	<i>Mounted on side, not front (4.15.4)</i>	<i>Replace with handicap approved</i>			<i>\$850</i>
<i>Telephone</i>	<i>Needs visually impaired "skirt" (4.4.1)</i>	<i>Modify as needed (Pac Bell)</i>	<i>N/A</i>		
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>			<i>\$800</i>
<b>Grand Total:</b>	<b>\$37,975</b>		<b>\$1,325</b>	<b>\$0</b>	<b>\$36,650</b>

*Total For Fiscal Year: \$1,325 \$0 \$36,650*

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**GOLVER PARK**

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
West restrooms	Entrance width is 30" (4.13.5)	Widen the doorway			\$1,500
Ticket booth	Has 48" height (max is 36") (4.2.5)	Alternative - have ticket seller assist handicapped patrons	N/A	N/A	N/A
Football stadium Women's restrooms	No handicapped stalls (4.17)	Build up handicap stall			\$3,500
	Handles inaccessible (4.24.7) No wrap for drain (4.24.6)	Change faucet to push-type controls Add wrapping	\$300 \$150		
Football stadium Men's restrooms	No handicapped stalls (4.17)	Build up handicap stall			\$3,500
	Handles inaccessible (4.24.7) No wrap for drain (4.24.6) Urinals are not accessible(4.18)	Change handle to push-type controls Add wrapping Install approved urinal at appropriate height	\$300 \$150	\$2,000	
General	Handicapped signage (4.30)	Install when accessibility complete			\$150
<b>Grand Total:</b>	<b>\$11,550</b>		<b>\$900</b>	<b>\$2,000</b>	<b>\$8,650</b>
			<b>Total For Fiscal Year:</b>		

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

IMPERIAL PARK

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Parking</i>	<i>No warning signs (4.6.4)</i>	<i>Install warning signs</i>	<i>\$0</i>	<i>\$0</i>	<i>\$0</i>
<i>Play areas</i>	<i>No accessible path way into the play area (4.5.1) Surface around play equipment is wood chips and unaccessible (4.33.4)</i>		<i>\$0</i>	<i>\$0</i>	<i>\$0</i>
<b><i>Grand Total:</i></b>			<b><i>\$0</i></b>	<b><i>\$0</i></b>	<b><i>\$0</i></b>

*Total For Fiscal Year:*

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

PEARSON PARK

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Pool Men's dressing room	Urinal to height (4.18.2)	Lower one urinal	\$750		\$6,000
	Sinks have no wrapping on drains (4.24.6)	Install wraps on sink pipes	\$150		
Women's room	None of three sinks have wrapping (4.24.6)	Install wraps on sink pipes	\$90		
Entrance to pool	No ramp into pool (4.8)	Install a ramp/or lift (advisory)			\$3,500
Greek Theater East men's room	Sink buttons too stiff (4.24.7)	Replace with handicapped approved units	\$400		
	No handicap signage (4.30)	Install accessibility signage	\$100		
Parking	No van handicapped parking (4.1.2.b)	Re-draw or combine existing lanes	\$400		
General	Handicapped signage (4.30)	Install when accessibility complete	\$100		
<b>Grand Total:</b>	<b>\$11,490</b>		<b>\$1,990</b>	<b>\$0</b>	<b>\$9,500</b>
			<b>Total For Fiscal Year: \$1,990 \$0 \$9,500</b>		

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

BROOKHURST COMMUNITY CENTER

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost</i>	<i>Est. Cost</i>	<i>Est. Cost</i>
			<i>FY 93/94</i>	<i>FY 94/95</i>	<i>FY 95/96</i>
<i>Women's restroom</i>	<i>No grab bar at the back of commode (4.26)</i>	<i>Install grab bar</i>	\$300		
	<i>No wrap for drain(4.24.6)</i>	<i>Add wrapping</i>	\$50		
	<i>No handicap Mirror (4.19.6)</i>	<i>Mount a mirror no higher than 40" above the floor</i>	\$200		
<i>Men's restroom</i>	<i>No grab bar at the back of commode (4.26)</i>	<i>Install grab bar</i>	\$300		
	<i>No wrap for drain(4.24.6)</i>	<i>Add wrapping</i>	\$50		
	<i>No handicap Mirror (4.19.6)</i>	<i>Mount a mirror no higher than 40" above the floor</i>	\$200		
	<i>No handicap urinal (4.18)</i>	<i>Lower one urinal maximum of 17" above floor</i>	\$700		
<i>Auditorium door</i>	<i>All 3 door's handle require twisting (4.13.9)</i>	<i>Change all hardware to lever type</i>		\$1,000	
<i>Meeting rooms' doors</i>	<i>All 7 door's handle require twisting (4.13.9)</i>	<i>Change all hardware to lever type</i>		\$2,300	
<i>Hallway doors</i>	<i>All 2 door's handle require twisting (4.13.9)</i>	<i>Change all hardware to lever type</i>		\$660	
<i>Women's restroom off of meeting room</i>	<i>No grab bar at the back of commode (4.26)</i>	<i>Install grab bar</i>	\$200		
	<i>No wrap for drain(4.24.6)</i>	<i>Add wrapping</i>	\$50		
	<i>No handicap Mirror (4.19.6)</i>	<i>Mount a mirror no higher than 40" above the floor</i>	\$200		

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**BROOKHURST COMMUNITY CENTER**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
	No handicap paper towel dispensers (4.16.6)	Install handicap paper towel dispenser	\$75		
	Door handle require twisting (4.13.9)	Change door hardware to lever type		\$330	
Men's restroom off of meeting room	No grab bar at the back of commode (4.26)	Install grab bar	\$300		
	No wrap for drain(4.24.6)	Add wrapping	\$50		
	No handicap Mirror (4.19.6)	Mount a mirror no higher than 40" above the floor	\$200		
	No handicap paper towel dispensers (4.16.6)	Install handicap paper towel dispenser	\$75		
	No handicap urinal (4.18)	lower one urinal	\$1,000		
	Door handle require twisting(4.13.9)	Change door hardware to lever type		\$330	
<b>Grand Total:</b>	<b>\$8,570</b>		<b>\$3,250</b>	<b>\$5,320</b>	<b>\$0</b>
			<b>Total For Fiscal Year:</b>		

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**MARTIN RECREATION CENTER**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
Restroom	Restroom door width 28" (4.13.5) None of the three commodes accessible need stall (4.17) Sinks have no handicapped handles (4.24.7) No wrap for drain (4.24.6) Men's urinals not accessible (4.18)	Door width should be 32" Construct new unisex restroom exclusive handicap use (see note below) Install push-type faucet	\$150		
Construct unisex restroom	Existing restroom inaccessible (4.22)	Construct new unisex restroom exclusive handicap use			\$35,000
Telephone	Nearby pay phone not accessible, too high (4.31.3)	Lower the phone	N/A		
Stage area	No rail, no handicapped access (4.33.5)	Install lift or ramp			\$1,200
Parking	Inadequate stall width for handicap van (4.6.3)	Re-stripe parking lot	\$450		
General	Handicapped signage (4.30)	Install when accessibility complete			\$250
<b>Grand Total:</b>	<b>\$37,100</b>		<b>\$650</b>	<b>\$0</b>	<b>\$36,450</b>
		<b>Total For Fiscal Year:</b>	<b>\$650</b>	<b>\$0</b>	<b>\$36,450</b>

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**OAK CANYON NATURE CENTER**

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Parking structure	No designated parking stalls(4.1.2)	Dirt lot - no lines - install signage as required less lines	\$250		
Restroom inside	Door hardware require twisting(4.13.9)	Install door hardware that does not require twisting or grasping	\$150		
	Napkin dispenser and soap containers are too high (4.16.6)	Lower the napkin dispenser and soap container	\$75		
	Seat cover dispenser is too high, 48" above the floor (4.16.6)	Lower seat cover to 40"	\$50		
	Faucet controls operate with tight grasping and twisting (4.19.5)	Install push-type Faucet	\$150		
Restrooms outside	No accessible signage (4.30)	Install accessible signage			\$150
General	Toilet seat is too low, 14" above floor (4.17)	Install raised type toilet seat	\$75		
	Handicapped signage (4.30)	Install when accessibility complete			\$150
<b>Grand Total:</b>	<b>\$1,050</b>	<b>Total For Fiscal Year:</b>	<b>\$750</b>	<b>\$0</b>	<b>\$300</b>

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**CITY HALL PUBLIC AREAS**

<b>Area</b>	<b>Non-compliance Issue</b>	<b>Recommendation/Resolve</b>	<b>Est. Cost FY 93/94</b>	<b>Est. Cost FY 94/95</b>	<b>Est. Cost FY 95/96</b>
B - building vestibule staircase	Outer Handrail not continuous through stair run (4.8.5)	Elevators can be used in lieu of staircase	N/A	N/A	
Elevators - all	No audible sound identifying floor number, four rings for fourth floor, etc. (4.10.4)	Modify system adding voice or bells			\$14,000
Restrooms - all public (8 units) Life safety systems	Stall width inadequate (4.17) Signaling device illumination not adequate	Remodel restroom, delete one fixture to allow increase in size of handicap stall every other floor Upgrade light/sound fire system to meet ADA requirements		\$36,000	\$36,000
Parking structure and lots	In-adequate stall width for handicap van parking (4.1.2)	Re-strip parking areas to allow increase in stalls	\$1,200		
General	Handicapped signage (4.30)	Install when accessibility complete			\$7,500
<b>Grand Total:</b>			<b>\$46,200</b>	<b>\$36,000</b>	<b>\$57,500</b>

**Total For Fiscal Year: \$46,200**

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

CONVENTION CENTER

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Hall A East Men's & Women's restrooms	Restrooms are not handicaps accessible Sink is not accessible(4.24) No handle on faucet (4.24.7) No handicap stall (4.17) Door width is 27" (4.13.5)	Lower sink Change faucet Remove one commode and build up handicap stall Door width should be 32"	\$1,000 \$300	\$2,500	\$1,500
Lanai restrooms	Men's & Women's Restrooms are not handicap accessible (4.22)	Use alternative handicaps restrooms located at lobby A or Arena lobby			
Arena restrooms	Men's & Women's Restrooms are not handicap accessible (4.22)	Demolition is in plan for YR 95/96, alternative restrooms are located at Arena lobby	N/A	N/A	N/A
Hall A Men's restrooms (2)	Sink is not accessible(4.24) No handle on faucet (4.24.7) No handicap stall (4.17) Urinal too high (4.18.2) No handicap mirror(4.19.6)	Lower sink Change handle on the faucet Remove one commode and build up handicap stall Lower one urinal maximum of 17" above floor Mount a mirror no higher than 40" above the floor	\$1,000 \$300 \$800 \$200	\$2,500	
Hall A Women's restrooms (2)	Sink is not accessible(4.24) No handle on faucet (4.24.7) No handicap stall (4.17) No handicap mirror(4.19.6)	Lower sink Change faucet Remove one commode and build up handicap stall Mount a mirror no higher than 40" above the floor	\$1,000 \$300 \$2,500 \$200		
Drinking fountain	Convention center is in process of replacing drinking fountains as there are expires. 8 units every year (4.15)	Install at least one handicap drinking fountain close by to groups of handicap restrooms. The cost of units per year	\$8,000	\$8,000	\$8,000

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**CONVENTION CENTER**

Area	Non-compliance Issue	Recommendation/Resolve	Est. Cost FY 93/94	Est. Cost FY 94/95	Est. Cost FY 95/96
Room B - Women's and Men's restrooms	Commode stall is 57" by 37" (4.17)	Need to modify stall		\$2,500	
	Sink is too high 35" (4.24)	Lower sink, no higher than 34" above floor	\$600		
	No wrap for drain(4.24.6)	Add wrapping	\$50		
	Toilet seat is high 21"(4.17)	Top surface must be 17" to 19" above floor	\$800		
	No grab bar at the back of commode(4.26)	Install grab bar	\$200		
	No handicap mirror(4.19.6)	Mount a mirror no higher than 40" above the floor	\$200		
Room C - Women's and Men's restrooms	No grab bar at the back of commode (4.26)	Install grab bar	\$200		
	Sink is too high 35" (4.24)	Lower sink, no higher than 34" above floor	\$600		
	No wrap for drain(4.24.6)	Add wrapping		\$2,500	
	Commode stall is inadequate too high(4.17)	Need to modify stall			
Hall C - Women's and Men's restrooms	No grab bar at the back of commode(4.26)	Install Grab bar	\$200		
	Sink is too high 35" (4.24)	Lower sink	\$600		
	No wrap for drain(4.24.6)	Add wrapping	\$50		

**City of Anaheim  
Facilities  
ADA Compliance Survey Report**

**CONVENTION CENTER**

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
Hall D ticket booth	No handicap signage (4.30)	Install accessible signage			
Administration office 2nd floor	No handicap access to 2nd floor (4.3)	Install 2-story elevator			\$160,000
<b>Grand Total:</b>			<b>\$206,600</b>	<b>\$15,500</b>	<b>\$169,500</b>
			<b>Total For Fiscal Year: \$21,600 \$15,500 \$169,500</b>		

*City of Anaheim  
Facilities  
ADA Compliance Survey Report*

UTILITY SERVICE CENTER

<i>Area</i>	<i>Non-compliance Issue</i>	<i>Recommendation/Resolve</i>	<i>Est. Cost FY 93/94</i>	<i>Est. Cost FY 94/95</i>	<i>Est. Cost FY 95/96</i>
<i>Parking</i>	<i>Not enough parking space (203 spaces) No van stalls (4.1.2.b)</i>	<i>Add 4-5 new handicapped stalls Add van stall -</i>		<i>\$500</i>	
<i>Building</i>	<i>No direct accessible route to the building</i>	<i>No feasible resolve</i>	<i>N/A</i>		
<i>Drinking fountain</i>	<i>Water fountain is not handicap accessible (4.15)</i>	<i>Install new fountain</i>		<i>\$800</i>	
<i>Restrooms - Mens and Womens</i>	<i>Restrooms are not handicaps accessible (4.22)</i>	<i>Modify existing restrooms to meet requirement</i>		<i>\$16,000</i>	
<i>General</i>	<i>Handicapped signage (4.30)</i>	<i>Install when accessibility complete</i>			<i>\$200</i>
<b><i>Grand Total:</i></b>			<b><i>\$0</i></b>	<b><i>\$17,300</i></b>	<b><i>\$200</i></b>
			<b><i>Total For Fiscal Year:</i></b>		
			<b><i>\$0</i></b>	<b><i>\$17,300</i></b>	<b><i>\$200</i></b>

